
From: [REDACTED]
Sent: Thur 5/15/2025 4:56:05 PM (UTC-04:00)
To: Bailey, Gregory [REDACTED]
Cc: [REDACTED] Nia-CSSO [REDACTED]
Subject: [External] Tall Ship NIAGARA - Non Reporting at Callin points
Attachment: Seaway Hand Book - Communication.pdf

***ATTENTION:** This email message is from an external sender. Do not open links or attachments from unknown senders. To report suspicious email, use the [Report Phishing button in Outlook](#).*

Good afternoon Capt. Bailey,

This is bring to your notice that Tall Ship NIAGARA did not follow Radio Communication calling-in procedure when the ship arrived in Port Colborne.

The vessel also needs to take directions from traffic Controller for docking. That was not done as well.

Please refer to attached pages Seaway Handbook for future reference.

Best regards,

(See attached file: Seaway Hand Book - Communication.pdf)

Capt. Rajendra (Raj) Phanse
Ship Inspector / Enforcement Officer
The St. Lawrence Seaway Management Corporation
508 Glendale Avenue, P.O.Box 370
St. Catharines, Ontario L2R 6V8
Tel 905 - 641 - 1932 x 5336
Cell 905 - 736 - 1468
Email [REDACTED]
Web www.greatlakes-seaway.com